

CAUTION

THIS IS AN UNVENTED ATTIC BY DESIGN

NO MODIFICATION MAY BE MADE TO THIS UNVENTED CONDITION. THE ATTIC SHALL NOT BE VENTED. HOLES INTO THE UNVENTED ATTIC SHALL BE IMMEDIATELY REPAIRED AND SEALED. PENETRATIONS OF THE CEILING OR WALL MEMBRANE BETWEEN THE UNVENTED ATTIC AND LIVING SPACE, OTHER THAN THE HORIZONTAL ATTIC HATCH, MUST BE PROTECTED IN AN APPROVED MANNER. THIS UNVENTED ATTIC SHALL NOT BE USED FOR STORAGE. SEE INTERTEK CODE COMPLIANCE RESEARCH REPORT CCRR-1063 ON THE INTERTEK WEBSITE, www.intertek.com.